

Site: GLENBURN CENTRE	Customer: EASTHALL PARK HOUSING
Contract No: ESC 205	Date: 1/10/19

Routine Tasks as per ACOP L8 & HSG 274 Part 2

Sentinel Outlets:

	Location	Mix °C	Hot °C	Cold °C		Location	Mix °C	Hot °C	Cold °C
Nearest Hot					Nearest Hot				
Nearest Cold					Nearest Cold				
Furthest Hot					Furthest Hot				
Furthest Cold					Furthest Cold				

No. of Calorifiers: **1** Purged: Yes No

Location	Flow °C	Return °C	Location	Flow °C	Return °C
KITCHEN	59.3	51.7			

Representative Outlets:

Location	Mix °C	Hot °C	Cold °C	Location	Mix °C	Hot °C	Cold °C
-1 KITCHEN	POU	41.4	15.3	GF GENTS	44.6	59.2	17.1
-1 GENTS	POU	43.6	15.2	GF CLEANERS			
GF KITCHEN	43.9	50.9	15.3				
DISABLED WC							

No. of CWST's: **1** Tank Temp °C Incoming MCW °C

Location	Tank Temp °C	Incoming MCW °C	Location	Tank Temp °C	Incoming MCW °C
ATTIC	16.8	15.9			

Showerhead / Spray Nozzles:

Clean / descale / disinfect showerheads Yes No No. of Showerheads / Spray Nozzles

Additional Information: **SITE VISIT TO CARRY OUT WATER TEMP CHECKS TO ACOP L8 LATEST EDITION**

(OCCUPANT REQUESTED TEMP FROM WATER DISPENSER ON FIDGE, 18.9°C)

Log Book Audit

Customers Signature: *Martin Gourlay* Cleartech Engineers Signature: *[Signature]*